

高级的国际新的国际公司的证据 医中间 经联系统 中面流行的 计多数分析 化化化铁铁 一切的女子的

USAF review(s) completed.

SECRET

25X1A

(IN-60814)

PAGE TWO (2)

IN TURNS AT HIGH MACH. AT 3.0 MACH OPENING BOTH AFT BY-PASS DOORS CAUSED INCREASE OF LEFT AND RIGHT EGT'S FROM 800 DEGREES TO 814 DEGREES. DOWN TRIMMED BOTH TO 800 DEGREES.

- 3. RETURNING TO TANKER THE LEFT ENGINE STALLED AT 2.14 MACH CLEARED AT 2 MACH. JOINED WITH TANKER, THE LEFT THROTTLE STUCK SO ABORTED REFUELING. CLIMB WAS MAT AT 445-450 KEAS. FORWARD BY-PASS DOORS OPEN INITIALLY WENT CLOSED AT 1.7 MACH. AT 2.0 MACH 450 KEAS THE RIGHT SPIKE BANGED, BUT DID NOT POP SHICK.
- 4. LANDING NORMAL, CHUTE NORMAL. PILOT NOTED THAT ARTICLE WAS VERY SENSITIVE LONGITUDINALLY AT 450 KEAS.

END OF MESSAGE